

8/12/81

DELETED Aug. 1980.

Superseded by DPM 6040.

THAT DELETED 1/30/81. NOT REPLACED

DDL DELETED

HAZ. FOLDERS - a MASTER UPDATED

COOP

Com. P.D. Form.

Pemaco

5989 District Blvd.

Los Angeles, CA 90040

DOUGLAS AIRCRAFT COMPANY

3855 Lakewood Boulevard Long Beach, California 90846

June 2, 1980

CI-725-0385

Joe will send
MSO sheet

Gentlemen:

By our letter CI-725-61 dated January 28, 1980, this office requested data as to the shipment of your product:

DPM 319-1 TO DPM 6040

Pems 1281

To Date, a reply has not been received.

As you know, we, as a reshipper of hazardous material, have the same responsibilities of the manufacturer and initial shipper as to being certain shipments of hazardous materials are properly described, classed, packaged, marked, labeled and certified according to the Hazardous Materials Regulations of the U. S. Department of Transportation, Title 49 CFR.

As a reshipper of your products, it is necessary we have required data on file to support this facility's compliance with the DOT Hazardous Materials Regulations. Therefore, your furnishing this requested data as soon as possible will be appreciated.

Very truly yours,

M. J. Veneroso, Branch Manager
Materials Handling & Packaging Engineering
Dept. CI-725 (52-11)
Douglas Aircraft Company

MJV/mf